

安全评价报告信息网上公示

项目概况	项目名称	中石油新疆销售有限公司阿克苏分公司拜城城西加油站安全现状评价		
	行业类别	石油加工业	报告提交时间	2026.2.14
	项目简介	中石油新疆销售有限公司阿克苏分公司拜城城西加油站于2015年建站开始运营，于2022年9月29日取得拜城县市场监督管理局颁发的最新营业执照，该站位于新疆阿克苏地区拜城县米吉克乡307省道90公里+200米处，负责人为田杰，该站的最新危险化学品经营许可证有效期限为2023年3月3日至2026年3月2日。许可范围：汽油、柴油。目前该站经营正常。 该站总占地面积4961m²，站房建筑面积为213.1m²，罩棚投影面积为644m²，罩棚下设有4台加油机，其中，2台双枪双油品潜油泵汽油加油机、1台双枪双油品潜油泵汽油柴油混合加油机、1台双枪单油品潜油泵柴油加油机，站内设4座双层储罐，该站油罐全部处于正常投用状态，其中2座30m³汽油储罐，2座50m³柴油储罐。总储量为160m³，折合储量为110m³（柴油罐容积折半计算），根据《汽车加油加气加氢站技术标准》（GB50156-2021）第3.0.9条规定属于二级加油站。		
安全评价项目参与人员	项目评价组长	张书杰	技术负责人	邹方永
	过程控制负责人	唐晓娟	报告编制人	张书杰
	报告审核人	徐志伟	安全评价师	刘红岩 张会平 臧怀壮 刘全进
	注册安全工程师	张书杰 刘红岩 张会平 刘全进 唐晓娟 邹方永	技术专家及技术人员	——
评价活动主要	安全评价类型	安全现状评价		
	到现场开展评价工作人员	张书杰 刘红岩（负责现场勘验人员）		

信息	到现场开展评价工 作时间及主要任务	2026.1.16 了解项目的基本情况、对现场进行勘验；2026.1.23 对 整改情况进行了复查。
	现场照片	 A photograph showing three men standing in front of a building entrance. The man on the left is wearing a grey jacket and a white hard hat, holding a white folder. The man in the middle is wearing a bright blue jacket and a red hard hat. The man on the right is wearing a dark blue jacket and a white hard hat, holding a black folder. Behind them is a white sign with Chinese text and a red and yellow striped awning. The sign reads: 中石油新疆销售有限公司阿克苏分公司 (Sinopec Xinjiang Sales Co., Ltd. Aksu Branch), 阿克苏市加康路 (Jiakang Road, Aksu City), 956109 (956109), 营业时间 00:00-24:00 (Operating Hours 00:00-24:00). To the right is a glass door with a colorful 'Happy New Year' (新年快乐) decoration.







		 
	备注及其他信息	无